



**Republic of the Philippines**  
**Department of Education**  
**REGION IV-A CALABARZON**  
**CITY SCHOOLS DIVISION OF CABUYAO**  
**DISTRICT 4A**  
**MARINIG SOUTH ELEMENTARY SCHOOL**

**DAMAGE ASSESSMENT PER BUILDING OF MARINIG SOUTH ELEMENTARY SCHOOL**

Department of Education - Education Services Division  
**DAMAGE ASSESSMENT PER BUILDING**

NAME OF SCHOOL: MARINIG SOUTH ES      DATE OF VISIT: MARCH 3, 2021  
 SCHOOL ID: F08245      INSPECTED BY: SARAH R. BUNEL  
 REGION: IV-A CALABARZON      INSPECTED BY:  
 DIVISION: CABUYAO  
 MUNICIPALITY: CABUYAO

Attachments: Site Development Plan and Photographs

Building Number	#1	#2	#3	#4	#5	#6	#7	#8	#9	#10
Building Type	APRIN	HEMPDES	AGULLA	PPP	CHIFECU	DEPED	DEPED	LA 2/12a		
Number of Storeys	3	2	2	2	1	4	1	2		
Total Number of Classrooms	6	4	4	4	2	8	2	4		
Classroom Dimension	7x9	7x9	7x6	7x9	7x8	7x9	7x9	7x8		
Classrooms still in use (Yes or No)	YES	YES	YES	YES	YES	YES	YES	YES		
Damaged by recent calamity (Yes or No)	NO	NO	NO	NO	NO	NO	NO	NO		
	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)	Damage Ratio (%)
<b>COMPONENTS</b>										
Roofing Sheets					50%					
Roofing Roll										
Plastering							100%	100%		
Plaster	100%	50%	100%							
Acacia Boards	50%				50%					
Corrals										
Russes										
Ceiling Boards (Exterior)	100%		25%		100%		100%			
Ceiling Frame (Exterior)										
Ceiling Boards (Interior)					50%					
Ceiling Frame (Interior)										
CHB Walls (Exterior)										
CHB Walls (Interior)										
Partition Wall (Boards)										
Partition Wall (Frame)										
Doors										
Windows (Front)			25%		35%			100%		
Windows (Rear)	100%				25%			100%		
Electrical Fixtures										
Electrical Wires										
Electrical Rough-ins										
Flooring					25%			100%		
Beams										
Columns										
<b>AVERAGE DAMAGE RATIO</b>	<b>10.67%</b>	<b>2.68%</b>	<b>6.25%</b>	<b>0</b>	<b>13.33%</b>	<b>0</b>	<b>5.02%</b>	<b>5.92%</b>		
NUMBER OF CLASSROOMS (Affected by Recent Calamity)										
TOTALLY DAMAGED										
PARTIALLY DAMAGED (Major)										
PARTIALLY DAMAGED (Minor)										
OR FURTHER INVESTIGATION										
IN GOOD CONDITION										
NUMBER OF CLASSROOMS (Not Affected by Recent Calamity)										
TOTALLY DAMAGED										
PARTIALLY DAMAGED (Major)										
PARTIALLY DAMAGED (Minor)										
OR FURTHER INVESTIGATION										
IN GOOD CONDITION										
ASSESSMENT	CRITERIA 1	CRITERIA 2								
Totally Damaged	80% - 100%	None								
Partially Damaged (Major)	10% - 79%	1. Estimated cost of repair should be more than P10,000 but not to exceed the budget ceiling (Change assessment to Totally Damaged if condition is not satisfied)								
Partially Damaged (Minor)	1% - 9%	1. Estimated cost of repair should not exceed P10,000 per classroom AND 2. No damage to columns, beams and exterior walls (Change assessment to Partially Damaged (Major) if conditions 1 and 2 are not satisfied)								
For Further Investigation	10% - 79%	1. When there is damage to structural components like beams and columns AND 2. Applicable only to Gabaldon Buildings and buildings two storeys and above								
In Good Condition	0%	None								

Prepared by:

**JUAN MARIO P. YUMENA**  
Teacher III

Noted:

**EMMANUEL B. CERDA**  
Principal II

