




Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL

SCHOOL BUILDING INVENTORY
(As of 2019-2022)

Building Inventory: Instructional Classroom: 31 SBM Room: 1 ICT Room: 1

Building Number	Building/Structure	Fund Source/s	Specific Fund Source/s	Number of Storeys	Number of Rooms by Design/Intent	Year Completed (if not provided, refer to building type)
1	Admin Office	LGU/SEF Funded	Provincial Fund	1	1	1997
2	Hemedes Bldg.	LGU/SEF Funded	Municipality Fund	3	6	2014
3	EtoKarunungan	LGU/SEF Funded	Municipality Fund	2	4	2003
4	Public-Private Partnership (PPP)	DepEd National/CWF	DepEd Budget	2	6	2014
5	Chipeco Bldg.	House of Representative /PDAF	Congressional initiative	1	3	2001
6	DPWH - DepEd 2	DepEd Nationa/CWF1	DepEd Budget	4	8	2016
7	DPWH - DepEd 1	DepEd Nationa/CWF1	DepEd Budget	2	2	2012
8	Lazaro Bldg.	LGU Funded/PDHF	Provincial Fund	2	4	2004
9	School Canteen	LGU Funded/SEF	Municipality Fund	2	2	2009





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL

DEPARTMENT OF EDUCATION
 CITY SCHOOLS DIVISION OF CABUYAO
 RECORDS UNIT
RECEIVED



Department of Education
 School Building Inventory Form
 (as of October 31, 2019)

BY: *[Signature]*
 DATE: 12/4/19 11:40
 2019-124-25

Region:	IV-A CALABARZON	School ID:	108245
Division:	LAGUNA	School Name:	MARINIG SOUTH ELEMENTARY SCHOOL

Table 1. Summary of Existing Building


Building Number ¹	Building Type ²	Fund Source/s ³	Specific Fund Source/s ⁴	Building Condition ⁵	Number of Storeys ⁶	Number of Rooms ⁷	Year Completed ⁸ (If not provided, refer to building type)	Classification of Building ⁹	Is building PWD accessible? ¹⁰ (Yes/No)	Have undergone major repair for the last 5 years? ¹¹ (Yes/No)	With Certificate of Acceptance? ¹² (Yes/No)	Is the school building included in the DepEd Book of Accounts? ¹³ (Yes/No)
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8	Col. 9	Col. 10	Col. 11	Col. 12	Col. 13
1	Admin Office	LGU Funded	Provincial Fund	Needs Minor Repair	1	1	1997	Permanent	Yes	No	No	Yes
2	Hernandez Bldg.	LGU Funded	Municipal	Good Condition	3	6	2014	Permanent	No	Yes	No	No
3	Erobarrungan	LGU Funded	Municipal	Good Condition	2	4	2003	Permanent	No	Yes	No	No
4	PPP	DepEd National	PPP	Good Condition	2	6	2014	Permanent	No	No	No	No
5	Chiquero	House of Representative	Congressional Initiative	Needs Major Repair	1	3	2001	Permanent	Yes	No	No	No
6	DPWH - DepEd 2	DepEd National	DepEd Budget	Good Condition	4	8	2015	Permanent	No	No	No	Yes
7	DPWH - DepEd 1	DepEd National	DepEd Budget	Good Condition	2	2	2012	Permanent	No	No	No	Yes
8	Lazaro Bldg.	LGU Funded	Provincial Fund	Good Condition	2	4	2004	Permanent	No	No	No	No
9	Canteen	LGU Funded	Municipal	Good Condition	1	1	2009	Permanent	No	No	No	No

Prepared by: *[Signature]*
 MARY LANE H. MARQUEZ
 School Facilities Coordinator

Certified True and Correct by: *[Signature]*
 ALFREDO MARQUIN
 School Head

Validated by: *[Signature]*
 ESPERANZA A. MAMINTA
 Planning Officer III
 Schools Division Office

Validated by: *[Signature]*
 SARAH B. CASTILLO
 Engineer III
 Schools Division Office





Republic of the Philippines
Department of Education
 REGION IV-A CALABARZON
 CITY SCHOOLS DIVISION OF CABUYAO
 DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL




Department of Education
 School Building Inventory Form
 (as of October 31, 2019)

Region :	IV-A CALABARZON	School ID :	108245
Division :	LAGUNA	School Name :	MARINIG SOUTH ELEMENTARY SCHOOL

Table 2. Existing Rooms per Building

Building Number ²	Room Number ¹⁴	Room Condition ¹⁵	Actual Usage/s ¹⁶	Room Dimension (in Meters) ¹⁷	
				Width	Length
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6
	2	Good Condition	Grade 5 Classroom	7.0	9.0
	3	Good Condition	Grade 5 Classroom	7.0	9.0
	4	Good Condition	Grade 3 Classroom	7.0	9.0
	5	Good Condition	Grade 5 Classroom	7.0	9.0
	6	Good Condition	Grade 5 Classroom	7.0	9.0
5	1	Needs Major Repair	Grade 1	7.0	8.0
	2	Needs Major Repair	Grade 1	7.0	8.0
	3	Needs Major Repair	Kinder	7.0	8.0
6	1	Good Condition	Grade 2 Classroom	7.0	8.0
	2	Good Condition	Grade 2 Classroom	7.0	8.0
	3	Good Condition	Grade 4 Classroom	7.0	8.0
	4	Good Condition	Grade 4 Classroom	7.0	8.0





Republic of the Philippines
Department of Education
 REGION IV-A CALABARZON
 CITY SCHOOLS DIVISION OF CABUYAO
 DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL




Department of Education
 School Building Inventory Form
 (as of October 31, 2019)

Region:	IV-A CALABARZON	School ID:	199245
Division:	LAGUNA	School Name:	MARINIG SOUTH ELEMENTARY SCHOOL

Table 2. Existing Rooms per Building

Building Number ¹	Room Number ²	Room Condition ³	Actual Usage/ ⁴	Room Dimensions (in Meters) ⁵	
				Width	Length
Col 1	Col 2	Col 3	Col 4	Col 5	Col 6
1	1	Good Condition	Office	8.0	9.0
2	1	Good Condition	ICT/SBM	7.0	9.0
	2	Good Condition	Grade 6 Classroom	7.0	9.0
	3	Good Condition	Grade 6 Classroom	7.0	9.0
	4	Good Condition	Grade 6 Classroom	7.0	9.0
	5	Good Condition	Grade 6 Classroom	7.0	9.0
	6	Good Condition	Grade 6 Classroom	7.0	9.0
3	1	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
	2	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
	3	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
	4	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
4	1	Good Condition	Grade 5 Classroom	7.0	9.0





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
School Building Inventory Form
(as of October 31, 2019)

Region :	IV-A CALABARZON	School ID :	108245
Division :	LAGUNA	School Name :	MARINIG SOUTH ELEMENTARY SCHOOL

Table 2. Existing Rooms per Building


Building Number ¹	Room Number ¹⁴	Room Condition ¹⁵	Actual Usage/s ¹⁶	Room Dimension (in Meters) ¹⁷	
				Width	Length
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6
	5	Good Condition	Grade 5 Classroom	7.0	8.0
	6	Good Condition	Grade 4 Classroom	7.0	8.0
	7	Good Condition	Grade 4 Classroom	7.0	8.0
	8	Good Condition	Grade 4 Classroom	7.0	8.0
7	1	Good Condition	Kinder	7.0	8.0
	2	Good Condition	Grade 2 Classroom	7.0	8.0
8	1	Good Condition	Grade 1 Classroom	7.0	8.0
	2	Good Condition	Grade 1 Classroom	7.0	8.0
	3	Good Condition	Grade 1 Classroom	7.0	8.0
	4	Good Condition	Grade 1 Classroom	7.0	8.0
9	1	Needs Minor Repair	Canteen	7.0	10.0

Prepared by: MARY JANE R. MARQUEZ
School Facilities Coordinator

Certified True and Correct: AURENE O. AMOQUIN
SCHOOL HEAD

Validated by: ESPERANZA A. MAMINTA
Planning Officer III
Schools Division Office

Validated by: SARAH B. CASTILLO
Engineer III
Schools Division Office





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
School Building Inventory Form
(as of October 31, 2019)

Region :	IV-A CALABARZON	School ID :	109245
Division :	LAGUNA	School Name :	Marinig South Elementary School

Table 3. Number of Temporary Learning Space (TLS) & Makeshift Rooms

Number of Temporary Learning Space		Number of Classes/Sections using TLS		Number of Makeshift Rooms		Number of Classes/Sections using makeshift rooms	
Col. 1	Col. 2	Col. 1	Col. 2	Col. 1	Col. 2	Col. 1	Col. 2
0	0			4	8		

Prepared by:

MARY JANE R. MARQUEZ
School/Facilities Coordinator

Certified True and Correct by:


AURELIO AQUINO
School Head

Validated by:

ESPERANZA A. MAMINTA
Planning Officer III
Schools Division Office

Validated by:

SARAH B. CASTILLO
Engineer III Schools Division Office





Republic of the Philippines
Department of Education
 REGION IV-A CALABARZON
 CITY SCHOOLS DIVISION OF CABUYAO
 DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
School Building Inventory Form
 (as of October 31, 2019)

Region : IV-A CALABARZON	School ID : 108245
Division: LAGUNA	School Name : MARINIG SOUTH ELEMENTARY SCHOOL

Table 4 A. Number of Water and Sanitation Facilities

Building Number	Number of Functional Toilet Bowls ¹⁸				Number of Non-Functional Toilet Bowls ¹⁹	Number of Sink/Washbasin ²⁰	Number of Urinals ²¹	Number of Urinal Trough ²²	With Septic Tank ²³ (Yes/No)	Number of Faucets ²⁴	
	Male	Female	PWD	Shared						With Water Supply	Without Water Supply
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8	Col. 9	Col. 10	Col. 11	Col. 12
1	0	0	0	2	0	3	0	0	Yes	4	1
2	0	0	0	6	0	5	0	0	Yes	6	1
3	0	0	0	4	0	5	0	0	Yes	7	0
4	1	1	0	3	0	3	2	0	Yes	2	0
5	0	0	0	3	0	2	0	0	Yes	3	0
6	4	9	0	1	1	8	0	4	Yes	21	3
7	0	0	0	2	0	2	0	0	Yes	4	0
8	0	0	0	4	0	4	0	0	Yes	4	1
9	0	0	0	1	0	3	0	0	Yes	7	1

Table 4 B. Stand-Alone Water and Sanitation Facilities

Number of Water Facilities ¹⁸				Number of Non-Functional Toilet Bowls ¹⁹	Number of Sink/Washbasin ²⁰	Number of Urinals ²¹	Number of Urinal Trough ²²	With Septic Tank ²³ (Yes/No)	Number of Faucets ²⁴	
Male	Female	PWD	Shared						With Water Supply	Without Water Supply
Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8	Col. 9	Col. 10	Col. 11	Col. 12
1	2	0	3	3	10	0	0	1	31	0

Prepared by:

 MARY JANE R. MARQUEZ
 School Facilities Coordinator

Certified True and Correct by:


 AURENE O. ALOQUIN
 School Head

Validated by:

 ESPERANZA A. MAMINTA
 Planning Officer III
 Schools Division Office

Validated by:

 SARAH B. CASTILLO
 Engineer III
 Schools Division Office





Republic of the Philippines
Department of Education
 REGION IV-A CALABARZON
 CITY SCHOOLS DIVISION OF CABUYAO
 DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
 School Building Inventory Form
 (as of October 31, 2019)

Region : IV-A CALABARZON	School ID : 108245
Division : LAGUNA	School Name : Marinig South Elementary School

Table 5. Existing Number of Usable Furnitures


Kinder Modular Table ²⁶	Kinder Chair ²⁷	Arm Chair ²⁸	School Desk ²⁹	Other Classroom Table ³⁰	Other Classroom Chair ³¹	DepEd New Design 2-Seater Table & Chair ³²		
						Elementary	JHS	SHS
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7		
13	74	1235	29	0	0	0	0	0

Prepared by: MARY JANE R. MARQUEZ
 School Facilities Coordinator

Certified True and Correct by: AUREY O. ALBUQUIN
 School Head

Validated by: ESPERANZA A. MAMINTA
 Planning Officer III
 Schools Division Office

Validated by: SALVADOR CRISTIANO
 Engineer III - Schools Division Office





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL




Department of Education
School Building Inventory Form
(as of October 31, 2019)

Region: IV-A CALABARZON	School ID: 108245
Division: LAGUNA	School Name: MARINIG SOUTH ELEMENTARY SCHOOL

Table 6. Other Facilities

Other Facilities <i>Col. 1</i>	Present in Campus? (Yes/No) <i>Col. 2</i>
Covered Court	<input checked="" type="radio"/> Yes <input type="radio"/> No
Gymnasium	<input type="radio"/> Yes <input checked="" type="radio"/> No
Entrance Gate	<input checked="" type="radio"/> Yes <input type="radio"/> No
Permanent Perimeter Fence	<input checked="" type="radio"/> Yes <input type="radio"/> No
Temporary Perimeter Fence	<input checked="" type="radio"/> Yes <input type="radio"/> No
Playground	<input type="radio"/> Yes <input checked="" type="radio"/> No
School Garden	<input checked="" type="radio"/> Yes <input type="radio"/> No
Solar Panel	<input type="radio"/> Yes <input checked="" type="radio"/> No


Prepared by:


MARY JANE R. MARQUEZ
School Facilities Coordinator

Certified True and Correct by:



AURENE O. ALOQUIN
School Head

Validated by:


ESPERANZA A. MAMINTA
Planning Officer III-Schools Division Office

Validated by:


SARAH B. CASTILLO
Engineer III-Schools Division Office





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL




Department of Education
 School Building Inventory Form
 (as of February 28, 2022)

Region: IV-A CALABARZON	School ID: 106245
Division: LAGUNA	School Name: MARINIG SOUTH ELEMENTARY SCHOOL
Longitude: 121.1574	Latitude: 14.27031

Table 1. Summary of Existing Building

Building Name/ Number ¹	Building Type ²	Fund Source/s ³	Specific Fund Source/s ⁴	Building Condition ⁵	Number of Storeys ⁶	Number of Rooms ⁷	Year Completed ⁸ (if not provided, refer to building type)	Classification of Building ⁹	Is building PWD accessible? ¹⁰ (Yes/No)	Have undergone major repair for the last 5 years? ¹¹ (Yes/No)	With Certificate of Acceptance? ¹² (Yes/No)	Is the school building included in the DepEd Book of Accounts? ¹³ (Yes/No)	Building Material ¹⁴	Date of Acquisition ¹⁵	Acquisition Cost ¹⁶	Book Value ¹⁷	Insurance Information ¹⁸
1	Admin Office	LGI Funded	Provincial Fund	Good Condition	1	1	1997	Permanent	Yes	No	No	Yes	Concrete, Stone, Glaz	N/A	N/A	N/A	N/A
2	Homedex Bldg	LGI Funded	Municipal	Good Condition	3	6	2014	Permanent	No	Yes	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
3	Itakanungtan	LGI Funded	Municipal	Good Condition	2	4	2003	Permanent	No	Yes	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
4	PPP	DepEd National	PPP	Good Condition	2	6	2014	Permanent	No	No	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
5	Chigeco	House of Representatives	Congressional Inheritance	Needs Major Repair	1	3	2001	Permanent	Yes	No	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
6	DPWH-DepEd 2	DepEd National	DepEd Budget	Good Condition	4	9	2015	Permanent	No	No	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
7	DPWH-DepEd 1	DepEd National	DepEd Budget	Good Condition	2	2	2012	Permanent	No	No	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
8	Lazaro Bldg	LGI Funded	Provincial Fund	Good Condition	2	4	2004	Permanent	No	No	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A
9	Canteen	LGI Funded	Municipal	Good Condition	1	1	2009	Permanent	No	No	No	No	concrete, Stone, Glaz	N/A	N/A	N/A	N/A

Prepared by: MARY JANE R. MARQUEZ School Property Custodian/ School Engineering Facilities Coordinator	Certified True and Correct by: AURENE G. ALOQUIN School Head	Validated by: TROY ALLAN PEIRON Planning Officer III (Schools Division Office)
Validated by: SARAH B. CASTILLO Engineer III (Schools Division Office)		





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
School Building Inventory Form
(as of February 28, 2022)

Region :	IV-A CALABARZON	School ID :	108245
Division :	LAGUNA	School Name :	MARINIG SOUTH ELEMENTARY SCHOOL

Table 2. Existing Rooms per Building


Building Number ¹	Room Number ¹⁹	Room Condition ²⁰	Actual Usage/s ²¹	Room Dimension (in Meters) ²²	
				Width Col. 5	Length Col. 6
1	1	Good Condition	Office	8.0	9.0
2	1	Good Condition	ICT/SBM	7.0	9.0
	2	Good Condition	Grade 6 Classroom	7.0	9.0
	3	Good Condition	Grade 6 Classroom	7.0	9.0
	4	Good Condition	Grade 6 Classroom	7.0	9.0
	5	Good Condition	Grade 6 Classroom	7.0	9.0
	6	Good Condition	Grade 6 Classroom	7.0	9.0
3	1	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
	2	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
	3	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
	4	Needs Minor Repair	Grade 3 Classroom	7.0	8.0
4	1	Good Condition	Grade 5 Classroom	7.0	9.0

Prepared by:
MARY JANE R. MARQUEZ
School Property Custodian/
School Engineering Facilities Coordinator

Certified True and Correct by:
AURENE O. ALOQUIN
School Head

Validated by:
TROY ALLAN PEDRON
Planning Officer III
(Schools Division Office)

Validated by:
SARAH B. CASTILLO
Engineer III
(Schools Division Office)





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
 School Building Inventory Form
 (as of February 28, 2022)

Region : IV-A CALABARZON	School ID : 108245
Division : LAGUNA	School Name : MARINIG SOUTH ELEMENTARY SCHOOL

Table 2. Existing Rooms per Building


Building Number ¹	Room Number ¹⁹	Room Condition ²⁰	Actual Usage/s ²¹	Room Dimension (in Meters) ²²	
				Width <i>Col. 5</i>	Length <i>Col. 6</i>
<i>Col. 1</i>	<i>Col. 2</i>	<i>Col. 3</i>	<i>Col. 4</i>		
	2	Good Condition	Grade 5 Classroom	7.0	9.0
	3	Good Condition	Grade 5 Classroom	7.0	9.0
	4	Good Condition	Grade 3 Classroom	7.0	9.0
	5	Good Condition	Grade 5 Classroom	7.0	9.0
	6	Good Condition	Grade 5 Classroom	7.0	9.0
5	1	Needs Major Repair	Grade 1 Classroom	7.0	8.0
	2	Needs Major Repair	Grade 1 Classroom	7.0	8.0
	3	Needs Major Repair	Kinder	7.0	8.0
6	1	Good Condition	Grade 2 Classroom	7.0	8.0
	2	Good Condition	Grade 2 Classroom	7.0	8.0
	3	Good Condition	Grade 4 Classroom	7.0	8.0
	4	Good Condition	Grade 4 Classroom	7.0	8.0

Prepared by:
 MARY JANE R. MARQUEZ
 School Property Custodian/
 School Engineering Facilities Coordinator

Certified True and Correct by:
 AURENE O. ALOQUIN
 School Head

Validated by:
 TROY ALLAN PEDRON
 Planning Officer III
 (Schools Division Office)

Validated by:
 SARAH B. CASTILLO
 Engineer III
 (Schools Division Office)





Republic of the Philippines
Department of Education
 REGION IV-A CALABARZON
 CITY SCHOOLS DIVISION OF CABUYAO
 DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL




Department of Education
 School Building Inventory Form
 (as of February 28, 2022)

Region : IV-A CALABARZON	School ID : 108245
Division : LAGUNA	School Name : MARINIG SOUTH ELEMENTARY SCHOOL

Table 2. Existing Rooms per Building

Building Number ¹	Room Number ¹⁹	Room Condition ²⁰	Actual Usage/s ²¹	Room Dimension (in Meters) ²²	
				Width	Length
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6
	5	Good Condition	Grade 5 Classroom	7.0	8.0
	6	Good Condition	Grade 4 Classroom	7.0	8.0
	7	Good Condition	Grade 4 Classroom	7.0	8.0
	8	Good Condition	Grade 4 Classroom	7.0	8.0
7	1	Good Condition	Kinder	7.0	8.0
	2	Good Condition	Grade 2 Classroom	7.0	8.0
8	1	Good Condition	Grade 1 Classroom	7.0	8.0
	2	Good Condition	Grade 1 Classroom	7.0	8.0
	3	Good Condition	Grade 1 Classroom	7.0	8.0
	4	Good Condition	Grade 1 Classroom	7.0	8.0
9	1	Good Condition	Canteen	7.0	10.0

Prepared by: MARY JANE R. MARQUEZ School Property Custodian/ School Engineering Facilities Coordinator	Certified True and Correct by: AURENE D. ALOQUIN School Head	Validated by: TROY ALLAN PEDRON Planning Officer III (Schools Division Office)	Validated by: SARAHB. CASTILLO Engineer III (Schools Division Office)
-----------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------	-----------------------------------------------------------------------------------------	--------------------------------------------------------------------------------





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
 School Building Inventory Form
 (as of February 28, 2022)

Region: IV-A CALABARZON	School ID: 108245
Division: LAGUNA	School Name: MARINIG SOUTH ELEMENTARY SCHOOL

Table 3. Number of Temporary Learning Space/s (TLS) & Makeshift Room/s.

Temporary Learning Space/s		Makeshift Room/s	
No. of Temporary Learning Space/s ²³	No. of Classes/Sections using Temporary Learning Space/s ²⁴	No. of Makeshift Room/s ²⁵	No. of Classes/Sections using Makeshift Room/s ²⁶
Col. 1	Col. 2	Col. 3	Col. 4
0	0	7	14

Table 4A. Existing Number of Water and Sanitation Facilities


Building Number ¹	Number of Functional Toilet Bowls ²⁷				Number of Non-Functional Toilet Bowls ²⁸	Number of Sink/Washbasin ²⁹	Number of Urinals ³⁰	Number of Urinal Trough ³¹	With Septic Tank ³² (Yes/No)	Number of Faucets ³³	
	Male	Female	PWD	Shared						With Water Supply	Without Water Supply
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8	Col. 9	Col. 10	Col. 11	Col. 12
1	0	0	0	2	0	2	2	0	No	4	0
2	0	0	0	6	0	6	6	0	No	5	1
3	0	0	0	4	0	4	4	0	No	8	0
4	0	3	0	2	2	5	5	2	No	3	2
5	0	0	0	3	0	2	3	0	No	3	0
6	4	4	0	1	2	9	9	4	Yes	12	3
7	0	0	0	2	0	2	2	0	No	2	0
8	0	0	0	4	0	4	4	0	No	8	0
9	0	0	0	1	0	1	1	0	No	1	0

Prepared by:
 MARY JANE R. MARQUEZ
 School Property Custodian/
 School Engineering Facilities Coordinator

Certified True and Correct by:
 AURENE O. ALOQUIN
 School Head

Validated by:
 TROY ALLAN PEDRON
 Planning Officer III
 (Schools Division Office)

Validated by:
 SARAH B. CASTILLO
 Engineer III
 (Schools Division Office)





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
School Building Inventory Form
 (as of February 28, 2022)

IV-A CALABARZÓN	School ID: 108245
LAGUNA	School Name: MARINIG SOUTH ELEMENTARY SCHOOL

Existing Number of Stand-Alone Water and Sanitation Facilities

Number of Functional Toilet Bowls ²⁷				Number of Non-Functional Toilet Bowls ²⁸	Number of Sink/Washbasin ²⁹	Number of Urinals ³⁰	Number of Urinal Trough ³¹	With Septic Tank ³² (Yes/No)	Number of Faucets ³³	
Male	Female	PWD	Shared						With Water Supply	Without Water Supply
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8	Col. 9	Col. 10	Col. 11
0	0	0	3	0	13	0	0	Yes	60	0

Table 5. Existing Number of Usable Furniture

Kinder Modular Table ³⁴	Kinder Chair ³⁵	Armchair ³⁶	School Desk ³⁷	Other Classroom Table ³⁸	Other Classroom Chair ³⁹	DepEd New Design 2-Seater Table & Chair ⁴⁰		
						Elementary	Junior High School	Senior High School
Col. 1	Col. 2	Col. 3	Col. 4	Col. 5	Col. 6	Col. 7	Col. 8	Col. 9
15	80	1346	29	0	0	0	0	0

Table 6. Other Facilities/Amenities

Type of Facilities/Amenities	Present in Campus? (Yes/No)		Type of Facilities/Amenities	Present in Campus? (Yes/No)	
Col. 1	Col. 2	Col. 3	Col. 3	Col. 4	Col. 5
Covered Court ⁴¹	<input checked="" type="radio"/> Yes	<input type="radio"/> No	Flood Marker ⁴⁶	<input type="radio"/> Yes	<input type="radio"/> No
Gymnasium ⁴²	<input type="radio"/> Yes	<input type="radio"/> No	Playground ⁴⁷	<input type="radio"/> Yes	<input type="radio"/> No
Solar Panel ⁴³	<input type="radio"/> Yes	<input type="radio"/> No	School Garden ⁴⁸	<input type="radio"/> Yes	<input type="radio"/> No
Permanent Perimeter Fence ⁴⁴	<input type="radio"/> Yes	<input type="radio"/> No	Entrance Gate ⁴⁹	<input type="radio"/> Yes	<input type="radio"/> No
Temporary Perimeter Fence ⁴⁵	<input type="radio"/> Yes	<input type="radio"/> No	Exit Gate ⁵⁰	<input type="radio"/> Yes	<input type="radio"/> No

Prepared by:

MARY JANE R. MARQUEZ
 School Property Custodian/
 School Engineering Facilities

Certified True and Correct by:


AURENE D. ALOQUIN
 School Head

Validated by:

TROY ALLAN PEDRON
 Planning Officer III
 (Schools Division Office)

Validated by:

SARAH B. CASTILLO
 Engineer III
 (Schools Division Office)





Republic of the Philippines
Department of Education
REGION IV-A CALABARZON
CITY SCHOOLS DIVISION OF CABUYAO
DISTRICT 4A
MARINIG SOUTH ELEMENTARY SCHOOL



Department of Education
School Building Inventory Form
(as of February 28, 2022)

Region :	IV-A CALABARZON	School ID :	108245
Division :	LAGUNA	School Name :	MARINIG SOUTH ELEMENTARY SCHOOL

Table 7. Access going to School
(Check all applicable)

Type of Access Road ⁵¹		Accessible by type of transportation ⁵²	
Col. 1		Col. 2	
<input checked="" type="checkbox"/>	Paved	<input checked="" type="checkbox"/>	Private 4-Wheel Vehicle
<input type="checkbox"/>	Unpaved	<input checked="" type="checkbox"/>	Private Motorcycle
<input checked="" type="checkbox"/>	Levelled	<input type="checkbox"/>	Boat
<input type="checkbox"/>	Unlevelled/ Rough road	<input type="checkbox"/>	UV Express
<input type="checkbox"/>	On-going construction	<input checked="" type="checkbox"/>	Pedicab
		<input checked="" type="checkbox"/>	Tricycle
		<input checked="" type="checkbox"/>	Jeepney
		<input type="checkbox"/>	Habal-habal
		<input type="checkbox"/>	Train
		<input type="checkbox"/>	Bus
		<input checked="" type="checkbox"/>	Walking/Hiking

Prepared by: MARY JANE R. MARQUEZ
School Property Custodian/
School Engineering Facilities
Coordinator

Certified True and Correct by: AURENE O. ALOQUIN
School Head

Validated by: TROY ALLAN PEDRON
Planning Officer III
(Schools Division Office)


Validated by: SARAH B. CASTILLO
Engineer III
(Schools Division Office)

Prepared by:

JUAN MARIO P. YUMENA
Teacher III

Noted:

EMMANUEL B. CERDA
Principal II



MASIGASIG
Batang Timog Marinig

